

# DAMAGE EXPERIENCE IN SOLAR THERMAL POWER PLANTS

Dr. Bernhard Persigehl  
Dresden / May 24<sup>th</sup>, 2019



# “LESSONS LEARNED FOR 85 YEARS”

Allianz Risk Consulting GmbH – Allianz Zentrum für Technik



1932 founded in Berlin as  
“**Materialprüfanstalt**” of Allianz  
Insurance



Since 1969 located at Munich  
**Allianz Zentrum für Technik**

- Commercially operated through Allianz Risk Consulting GmbH
- 2007 integrated into AGCS

Root Cause Analyses

Lessons Learned

Risk Assessments


Turbo-  
machines



Materials  
Corrosion



Monitoring



Fire Protection



Electrical  
Engineering



Non-  
Destructive  
Testing



Mechanical  
Engineering




Chemistry,  
Process Eng.



Laboratory  
Analyses


- SEM
- Optical Micr.
- RFA
- Hardness
- Etc.

# CONCENTRATED SOLAR POWER (CSP) – 2 MAIN TECHNOLOGIES



Parabolic Trough Power Plant

# CONCENTRATED SOLAR POWER (CSP) – 2 MAIN TECHNOLOGIES






# CONTENT

- 01** DAMAGES EXAMPLES
- 02** ROOT CAUSE ANALYSES
- 03** SUMMARY




# DAMAGE EXAMPLES





# NATURAL PERILS



Windstorm




Tornado



Flood

# COLLECTOR EXPLOSION




Damage due to:  
Welding Error during Assembly

Small leakage lead to Ignition of Heat Transfer Fluid (HTF, thermal oil)



# SALT TANKS




## Problem:

- Cold salt immediately crystallizes
- Tank only accessible from the top
- Tank has to be completely drained
- 6 month standstill




## Root Cause:

- The salt inlet pipes were welded to the tank.
- Overdetermined
  - No degree of freedom for thermal growth
  - Crack initiation to the tank





# PROBLEMS WITH HELIOSTATS

## 1. DOUBLE BLOCKING



# PROBLEMS WITH HELIOSTATS –

## 2. ALIGNMENT





### Problems with Alignment:

- Too many heliostats concentrated at one point → energy density too high
- Heliostats are aligned before HTF is flowing through receiver



# ALIGNMENT ISSUE



## Problem:

The rotating position of several heliostats could not be controlled as requested.

## Root Cause:

An inappropriate firmware within the encoders led to interruption of the communication between the encoders and the PLCs during start-up.

## Repair Solutions:

- Change of all encoders → very expensive
- New PLCs → risky
- Implementation of an additional relay in front of each encoder to avoid the communication problem





# CONTENT

**01** DAMAGES EXAMPLES

**02** ROOT CAUSE ANALYSES



DAMAGED HTF TUBES

CLOCKED STEAM TURBINE

RUBBING EVENT IN STEAM TURBINE

**03** SUMMARY

# HTF TUBES




## Technical Issue / Loss:




2.500/22.000 cracked glass tubes shortly after commissioning.

Manufacturing issue or faulty assembling?

# LABORATORY ANALYSES




The found defects are not the cause of the damage!



Fracture Level

# ANALYSES OF OPERATIONAL DATA



Measured temperature gradients of 200K during one day



FEM calculation showed that the resulting high stresses are not critical for intact glass tubes.



# ROOT CAUSE



Scratch


## Cause of fractures:

During the installation of the receiver tubes the glass surface was scratched onsite during the assembly of the metal insulation.

Due to the high thermal loads during start and stops the scratched tubes broke.

Why were there scratches at the glass tube surfaces?

# FACILITATING EFFECT



Original design




Design of a local sub-contractor



No sharp edges, no boreholes, plug-in connection



Many sharp edges, boreholes for the rivet connection



## Lessons Learned:

Local sourcing from inexperienced sub-supplier can cause critical quality issues.

# CLOCKED STEAM TURBINE

Steam turbine showed reduced performance after two years of operation.

→ Borescope inspection revealed deposits in few stages in the middle of the steam turbine.



Stage with deposits



Stage without deposits

Opening of the turbine necessary

→ Analysis of the deposits showed mainly Aluminum

How can there be aluminum in the water steam cycle?


# SOURCE OF THE ALUMINUM

In the economizer, aluminum swirlers were implemented to improve the heat transfer.

Event reported during commissioning:

„Due to problems with the water treatment the pH-value was too high leading to a rapid degradation (dissolution) of the aluminum swirlers. The system was cleaned and stainless steel swirlers were implemented.“

Residuals of Aluminum stayed in the system. They agglomerated in the affected stages, since the arising temperature of 300°C fits to a level change of the aluminum oxide.



Be careful!!!

This root cause analysis sounds correct for a mechanical engineer (with low knowledge of chemistry and materials).


There must not have been a problem with the pH-value during commissioning. It is generally not possible to adjust the pH-value correctly for aluminum and steel.

→ Design Issue






# DAMAGED LOW PRESSURE STEAM TURBINE




Low Pressure Turbine

# DAMAGE PATTERN

Bended and back-twisted blades (randomly distributed) at second final stage within low pressure turbine from hard contact with casing



White: un-damaged profile  
Green: back-twisted profile  
Blue: bended profile




**flow direction**

# DAMAGE ROOT CAUSE

Water / (cool) steam hammer on the blades

The last steam extraction within the turbine was not correctly drained (manually).

→ Water hammer on the blades



Water Hammer

Most stressed region

FE analysis of a water hammer




Crack found at most stressed region



Opened up crack shows only signs of forced fracture

## Lessons Learned:

A daily started steam turbine must be equipped with automatically operated valves for drainage!





# CONTENT

- 01** DAMAGES EXAMPLES
- 02** ROOT CAUSE ANALYSES
- 03** SUMMARY



# SUMMARY

Specific operation conditions in solar thermal power plants (low steam temperature, high temperature gradients) result in changed stresses of „well-established“ components such as steam turbines or heat exchangers. In combination with design weakness or manufacturing errors, this can lead to significant damages.

A learning curve has to be passed with „new“ components such as heliostats or parabolic troughs. Sub-contractors from another industry sector should be qualified appropriately.



My actual case 😊


# THANKS A LOT FOR THE ATTENTION!

## Dr. Bernhard Persigehl

Turbomachinery, Power Plant Engineer.  
Allianz Risk Consulting GmbH  
Allianz Center for Technology

Phone: +49.89.3800 – 13702

Email: [bernhard.persigehl@allianz.com](mailto:bernhard.persigehl@allianz.com)



## Dr. Johannes Stoiber

Management, Materials Science  
Allianz Risk Consulting GmbH  
Allianz Center for Technology

Phone: +49.89.3800 – 6329

Email: [johannes.stoiber@allianz.com](mailto:johannes.stoiber@allianz.com)



## Rudolf Weber

Corrosion, Materials Science  
Allianz Risk Consulting GmbH  
Allianz Center for Technology

Phone : +49.89.3800 – 6246

Email: [rudolf.weber1@allianz.com](mailto:rudolf.weber1@allianz.com)



# Questions??

